



## Excessive Oil Consumption on 2011-2015 Subaru 2.0 & 2.5L Engines

The AERA Technical Committee offers the following information on an excessive amount of oil consumption on 2011-2015 Subaru 2.0 & 2.5L engines. It is important to note that this information refers to Subaru's FA and FB engines which are commonly known as "Timing Chain" engines.

Recently, Subaru extended the warranty period for these engines to include the category of excessive oil consumption. Continued consumer complaints of oil consumption may have contributed to their extending short block replacement for certain vehicles. If oil consumption is experienced on the engines listed in the chart below, contact a Subaru dealer for evaluation of that condition.

MODEL	MODEL YEAR	TRANSMISSION	STARTING VIN	ENGINE NUMBER
Forester	2011-14	MT	All	All
	2015		Below F*543624	Below 527514
	2011-13	4AT or CVT	All	All
	2014		Below E*529004	Below 132164
Impreza 4- & 5-Door	2012-14	MT	All	All
	2015		Below F*270253	Below 627010
Impreza 4-Door	2012	CVT	All	All
	2013		Below D*033336	Below 930025 (FA1 Line*) or 652640 (FB2 Line*)
Impreza 5-Door	2012	CVT	All	All
	2013		Below D*886714	Below 930025 (FA1 Line*) or 652640 (FB2 Line*)
Legacy	2013-14	MT	All	All
	2013	CVT	Below D*048086	Below 151602
Outback	2013-14	MT	All	All
	2013	CVT	Below D*321435	Below 151602
XV Crosstrek	2013-14	MT	All	All
	2015		Below F*270284	Below 627010
	2013	CVT	Below D*856139	Below 930025 (FA1 Line*) or 652640 (FB2 Line*)

This information is provided from the best available sources. However, AERA does not assume responsibility for data accuracy or consequences of its application. Members and others are not authorized to reproduce or distribute this material in any form, or issue it to their branches, divisions, or subsidiaries, etc. at a different location, without written permission.